

## MODIS STRAY LIGHT TESTS

1) Near Field Response	PC04	SCMA	in Plan	All bands, subset of (2)
2) Point Spread Function	STR	SCMA	in Plan	All Bands, combine with (1)
3) Far Field Response	STR	SCMA + Laser Fixtures	New	Use 2W laser diode, tilt SCMA continue to explore
4) Stray Light in Nadir Port	PC12	Sun Gun	in Plan	Minor extension of existing test
5) Stray Light in SD Port	PC18	TBD	Deleted	Use of SCMA requires major fixture. Not likely
6) SRCA Earthshine	STR	TBD	New	Combine with (4) - turn on SRCA
7) SDSM Angular Dependence	STR	Optics Lab	in Plan	Substitute post-launch YAW
8) SRCA in Ambient MCC	PC17	MCC	New	Is this useful?
9) Adding Heater to NAD	T/V	MCC	in Plan	OK (glad to see)
10) Solar Diffuser Radiometry	PC18	TBD	Deleted	OK (Heliostat test)